
CFE Hot Fix Release Notes for MC17 CE5, MC91 CE6 & MC92 CE7/W6.5 - PB 3.1.0.9 - SPR 26218, 26689 & 27573

[Introduction](#)

[Description](#)

[Contents](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Device Compatibility](#)

[Version Number and Release Date](#)

Introduction

Mobile applications are key to leveraging the power, value and return on investment of your mobile solutions. Pocket Browser can significantly reduce the time and cost associated with mobile application development. This feature-rich, mobile application development tool is designed to allow Web developers to rapidly create robust mobile applications that can include a wide range of advanced data capture capabilities. Whether you want to streamline your warehouse, delivery or service operations, or enable more robust asset tracking or visibility, Pocket Browser will help you get your enterprise mobility solution up and running faster and more cost efficiently.

HotFix CFE (Cumulative Fixes from Engineering) Package includes multiple SPR Hotfixes contained into a single package. The HotFix CFE Package helps the end users to keep up to date with all the SPR hotfixes for given product software release / revision.

HotFix CFE packages are validated only by engineering validation team and the package follows Zebra Technologies HotFix Package Policy. Click here to view HotFix Package Policy. [HotFix Support Policy](#)

Description

In this hot fix CFE the following issues have been resolved:

SPR NO	Synopsis
26218	Pocket Browser (PB) v3.1 crashes when "NavTimeout" value exceeds 45000ms on W65/CE5/6/7 devices.
26689	Pocket Browser (PB) v3.1 breaks the move-ability of the SIP on CE5/6 devices.
27573	Pocket Browser (PB) v3.1 does not allow "Javascript:document.location.replace('test.jsp')" navigation on CE6/7 devices.

Content

PBv3109_CFE_WB.cab - PB hotfix package with Warm boot

PBv3109_CFE_NB.cab - PB hotfix package without Warm boot

Installation Requirements

The following prerequisites are required before installing this hot fix:

- Microsoft ActiveSync or Windows Mobile Device Center
- Pocket Browser version 3.1.0.1 installed on the device

Installation Instructions

For Normal installation of the PATCH:

- Windows Mobile Device Center (For Windows Desktops) Installation Instructions:
 1. Copy "PBv3109_CFE_WB.cab" file to the Application folder on the device.
 2. Deploy the solution by tapping on the "PBv3109_CFE_WB.cab" file.
 3. After successful deployment of the "PBv3109_CFE_WB.cab" file, device will do an automatic warm boot.
- SD Cards / Micro SD cards Installation Instructions(Aplicable for MC91 and MC92):
 1. Copy "PBv3109_CFE_WB.cab" file to the SD card.
 2. Deploy the solution by tapping on the "PBv3109_CFE_WB.cab".
 3. After successful deployment of the "CFE PBv3109_CFE_WB.cab" file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

1. Set up MDM (MSP, Soti, Airwatch, etc..) to send " PBv3109_CFE_NB.cab" file to the application folder of the device.
2. To deploy the solution, setup in MDM to install the cab file " PBv3109_CFE_NB.cab" file.
3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Device Compatibility

The hot fix has been validated for the following devices and platforms:

Device	Operating System
MC17	CE 5.0
MC9190	CE 6.0
MC92N0	CE 7.0/WM 6.5

Version Number and Release Date

Pocket Browser 3.1.0.9 - Jun 2015.

Accumulated Fixes:

Pocket Browser 3.1.0.1