



Xplore Technologies Software Release Note

Name	Intel Bluetooth Driver
File Name	Bluetooth_21.40.0.1
Release Date	June 16, 2020
This Version	21.40.0.1
Replaces Version	All previous versions
Intended Product	XBOOK L10, XPAD L10, XSLATE L10
File Size	473 KB
Supported Operating System	Windows 10

Fixes in this Release

- Skype voice drop when connect BT headphone and BT mouse
- BT link loss observed during large file transfer

What's New in this Release

-

Installation and Configuration Instructions

To install the Bluetooth Driver 21.40.0.1 update, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Right-click the installer (BT_install.cmd) and select 'Run as administrator'.
4. The update process completes quickly with no additional user action.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.