



Xplore Technologies Software Release Note

Name	Intel Bluetooth Driver
File Name	Intel_BT_Win10_21.120.0.4.zip
Release Date	November 10, 2020
This Version	20.70.18.2
Replaces Version	All previous versions
Intended Product	XBOOK L10, XPAD L10, XSLATE L10, XSLATE R12
File Size	1 MB
Supported Operating System	Windows 10 (64-bit)

Fixes in this Release

- Random BT disappear after Airplane mode Off/On

What's New in this Release

-

Installation and Configuration Instructions

To install the BT Driver 21.120.0.4 update, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Right-click the installer (BT_install.cmd) and select 'Run as administrator'.
4. The update process completes quickly with no additional user action.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.